

Release Notes - Hardware Rev D and Below

Public Release

Version 1.0.7	
Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Changed the default output resolution from 720p60 to Native. NOTE: Firmware 1.0.7 is to be used with the AT-HDVS-150-TX running version 1.0.7.
Known Issues	<ul style="list-style-type: none">• None

Previous Release

Version 1.0.6	
Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Fixed an issue where the Auto Off (sec) timer was not configurable using the OSD menu system.
Known Issues	<ul style="list-style-type: none">• None

Version 1.0.3	
Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Fixed an issue where Audio settings were not saved after the receiver loses power.• Fixed an issue where power-cycling the unit causes the receiver to send a reboot command, over RS-232, regardless of the system state.
Known Issues	<ul style="list-style-type: none">• None

Version 1.0.2	
Features	<ul style="list-style-type: none">• None
Bug Fixes	<ul style="list-style-type: none">• Unit no longer locks up when receiving an unrecognized resolution• Resolved issue where the unit sends a power command when it is power cycled
Known Issues	<ul style="list-style-type: none">• None

Version 1.0.0	
<ul style="list-style-type: none">• Factory Firmware	