

## Release Notes - Hardware Rev E and Above

### Public Release

Version 2.0.01	
Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Changed the default output resolution from 720p60 to Native. NOTE: Firmware 1.0.7 is to be used with the AT-HDVS-150-TX running version 2.0.01.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

### Previous Release

Version 2.0.0	
Features	<ul style="list-style-type: none"><li>• Hardware update</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• None</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

Version 1.0.6	
Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Fixed an issue where the Auto Off (sec) timer was not configurable using the OSD menu system.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

Version 1.0.3	
Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Fixed an issue where Audio settings were not saved after the receiver loses power.</li><li>• Fixed an issue where power-cycling the unit causes the receiver to send a reboot command, over RS-232, regardless of the system state.</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

Version 1.0.2	
Features	<ul style="list-style-type: none"><li>• None</li></ul>
Bug Fixes	<ul style="list-style-type: none"><li>• Unit no longer locks up when receiving an unrecognized resolution</li><li>• Resolved issue where the unit sends a power command when it is power cycled</li></ul>
Known Issues	<ul style="list-style-type: none"><li>• None</li></ul>

Version 1.0.0	
<ul style="list-style-type: none"><li>• Factory Firmware</li></ul>	