

Release Notes

Public Release

Version 2.0.3	
Features	• N/A
Bug Fixes	 Touch panel advanced menu is now accessible after the unit has been synced with Velocity.
Known Issues	• N/A

Previous Releases

Version 1

• Factory Firmware